



R1003X10




$D_a = 11 \pm 2$
 $D_i = 4 \pm 2$
 $B = 4.5 \pm 2$
 $L = 15 + 25$


R1003X11



R1003XKS



R1003XB5



R1003X-SMD

